

MODELL
990-102-007

**Externer Buna-N Dichtsatz, Serie 2 Ventile mit T-2A
Einschraubbohrung
EINSCHRAUBBOHRUNG: T-2A**

KOMPONENTEN

Part	Beschreibung	Anzahl
500-001-118	O-Ring	1
500-002-115	O-Ring	1
500-002-117	O-Ring	1
525-002-115	Backup Ring	1
525-002-118	Backup Ring	1
550-004-002	Backup Ring	1
999-019-034	Literature	1

BEMERKUNGEN

Install back-up rings and O-rings as shown in views.


See installation variations for models associated with alternative installation views.

When installing continuous back-up rings, use the same technique and the same care used to install O-rings.

When installing cartridge - be sure to torque to recommended value.

During 1985, SUN made a running change of all external seals on Series 2 cartridges (1-1/8 in. (28,6 mm) hex, 1-14 thd). The seals were changed from 3/32 in. (2,62 mm) c/s to 1/16 in (1,7/8 mm) c/s o-rings and backup rings.

Use the kit which contains the same size (c/s) seals as those used on the cartridge being repaired. Do not change cartridge o-ring c/s sizes.



TECHNISCHE EIGENSCHAFTEN

- Das Verfalldatum für einen Buna-N Ventildichtsatz beträgt 10 Jahre ab Kaufdatum. Dieses Datum steht auf dem Dichtsatzbeutel.

Copyright © 2002-2014 Sun Hydraulics Corporation. All rights reserved.